


**TABLE OF EXISTING TREES\***

Tree #	Species	DBH	Save/Remove
1	BLM	28"	Remove
2	A	20"	Remove
3	A	15.5"	Remove
4	BLM	18.5"	Remove
5	BLM	12"	Save
6	A	14.5"	Remove
7	BLM	14"	Save
8	EL	8"	Remove
9	A	18"	Remove
10	BLM	12.5"	Save
11	BLM	22"	Save
12	A	15.5"	Save
13	A	19.5"	Remove
14	A	19"	Remove
15	A	16"	Remove
16	A	21.5"	Remove
17	A	14"	Remove
18	A	19"	Remove
19	BLM	12"	Save
20	A	17"	Remove
21	A	16"	Remove
22	A	12.5"	Save
23	A	19"	Save
24	A	20"	Remove
25	BLM	15.5"	Remove
26	BLM	13.5" + 7"	Save
27	BLM	12"	Save

\* Per Feb 10, 2020 Field Visit by Michael Oxman, ISA Certified Arborist®  
 ISA Tree Risk Assessment Qualification  
[www.treedr.com](http://www.treedr.com)

 Disturbed Land:  
3,749 SF

**Nest.life**  
**Development LLC**  
 10400 SW Cowan Rd.  
 Vashon, WA 98070  
 407-455-3895

**Parcel #888700-1380**  
 111xxx 99th Ave SW  
 Vashon, WA 98070

Mar 9, 2020

Site Plan