

TABLE OF CONTENTS

EXECUTIVE SUMMARY	1
BUSINESS INSPECTIONS	1
SOURCE TRACING	1
<i>General observations and comparisons based on samples collected since January 2003.....</i>	<i>2</i>
PHTHALATE SOURCE STUDY	2
<i>Spill Kit Incentive Program</i>	<i>3</i>
<i>Residential Outreach Project.....</i>	<i>3</i>
NEXT STEPS	3
INTRODUCTION	5
OVERVIEW OF LOWER DUWAMISH WATERWAY-WIDE SOURCE CONTROL ACTIVITIES.....	6
BUSINESS INSPECTIONS	7
<i>Summary for the January 2005-June 2005 Reporting Period.....</i>	<i>8</i>
SOURCE TRACING	9
<i>Key Manhole Samples.....</i>	<i>10</i>
<i>Sediment Trap Samples.....</i>	<i>10</i>
<i>Catch Basin Samples.....</i>	<i>11</i>
<i>Inline Sediment Samples</i>	<i>13</i>
<i>Source Sediment Comparisons.....</i>	<i>14</i>
PHTHALATE SOURCE STUDY	15
<i>Atmospheric Deposition Sampling.....</i>	<i>15</i>
MISCELLANEOUS SOURCE CONTROL ACTIVITIES	17
<i>Surface Water Quality Complaints</i>	<i>17</i>
<i>Spill Kit Incentive Program</i>	<i>18</i>
<i>Business Outreach.....</i>	<i>18</i>
<i>Residential Outreach Project.....</i>	<i>18</i>
DIAGONAL/DUWAMISH EARLY ACTION SITE	20
BUSINESS INSPECTIONS	20
<i>Key Findings</i>	<i>21</i>
SOURCE SAMPLING AND IDENTIFICATION	21
<i>In-Line Sediment Traps.....</i>	<i>21</i>
<i>Catch Basin Samples.....</i>	<i>22</i>
<i>Inline Sediment Samples</i>	<i>22</i>
SOURCE CONTROL ACTIONS.....	23
<i>Diagonal Ave S CSO/SD Cleaning.....</i>	<i>23</i>
SLIP 4 EARLY ACTION SITE	24
BUSINESS INSPECTIONS	24
SOURCE TRACING	25
<i>Sediment Trap Samples.....</i>	<i>25</i>
<i>Inline Sediment Samples</i>	<i>25</i>
<i>Georgetown Flume Investigation.....</i>	<i>26</i>
<i>Catch Basin Samples.....</i>	<i>27</i>
FORMER SLIP 5 AND SLIP 6	28
BUSINESS INSPECTIONS	28
SOURCE TRACING	29
TERMINAL 117 EARLY ACTION SITE	30
SOURCE CONTROL ACTIONS.....	30
<i>Dallas Ave S Interim PCBs Cleanup.....</i>	<i>30</i>

NORFOLK EARLY ACTION SITE	32
NEXT STEPS.....	33
BUSINESS INSPECTIONS	33
<i>Diagonal/Duwamish</i>	33
<i>Slip 4</i>	33
<i>Terminal 117</i>	33
<i>Other Areas in the LDW</i>	33
SOURCE SAMPLING.....	34
<i>Source Tracing</i>	34
<i>Phthalate Source Study</i>	34
<i>Site-Specific Source Control Actions</i>	35
REFERENCES	36

TABLES

Table 1.	Corrective actions requested by program area.
Table 2.	Most frequent corrective actions requested.
Table 3.	Diagonal Ave S CSO/SD sediment trap results.
Table 4.	Construction projects in the Lower Duwamish Waterway.
Table 5.	Onsite catch basin sediment sample results.
Table 6.	Right-of-way catch basin sediment sample results.
Table 7.	Inline sediment sample results.
Table 8.	Source sediment comparisons.
Table 9.	Atmospheric deposition samples.
Table 10.	Atmospheric flux deposition measurements relative to Beacon Hill station.
Table 11.	Surface water quality complaints in the Lower Duwamish Waterway.
Table 12.	Businesses that received spill kits during the January – June 2005 reporting period.
Table 13.	Land use in the Diagonal Ave S CSO/SD service area.
Table 14.	Condition of Georgetown flume.
Table 15.	Active pipes entering Georgetown flume.
Table 16.	Dallas Ave S and vicinity sample results.
Table 17.	Dallas Ave S soil cleanup: Temporary stormwater treatment plant sample results.

FIGURES

Figure 1.	Lower Duwamish study area.
Figure 2.	Outfalls in the Lower Duwamish Waterway.
Figure 3.	Business inspected, March 2003 – June 2005.
Figure 4.	Source sample locations in the Lower Duwamish Waterway.
Figure 5.	Source sediment PCB comparisons.
Figure 6.	Source sediment BEHP comparisons.
Figure 7.	Wet/dry atmospheric deposition sampler.
Figure 8.	Air deposition sampling stations.
Figure 9.	Diagonal Ave S CSO/SD drainage basin boundary.
Figure 10.	Land use in the Diagonal Ave S CSO/SD service area.
Figure 11.	Business inspections in the Diagonal Ave S CSO/SD service area.
Figure 12.	Diagonal Ave S CSO/SD sediment trap locations.
Figure 13.	Catch basin samples collected in Diagonal Ave S CSO/SD service area.
Figure 14.	Diagonal Ave S CSO/SD cleaning project.
Figure 15.	Areas draining to Slip 4.
Figure 16.	Business inspected in Slip 4, June 2004 – June 2005.
Figure 17.	Slip 4 source sediment samples.
Figure 18A.	Upper Georgetown flume.

- Figure 18B. Lower Georgetown flume.
- Figure 19. Georgetown flume sediment sample locations and PCB results.
- Figure 20. Business inspected in Slip 5 and Slip 6.
- Figure 21. T117 drainage area.
- Figure 22. Sediment sample locations in the vicinity of T117 early action site.
- Figure 23. Dallas Ave S and vicinity street and yard sample locations.
- Figure 24. Dallas Ave S interim cleanup.
- Figure 25. Sediment sampling locations in Norfolk-MLK Way drainage system.

APPENDICES

Appendix A. Business inspection process and field form.

Appendix B. Data base output.

Table B-1. Summary of inspections completed January 2005 – June 2005.

Table B-2. Site summary reports for all areas inspected (January 2005 – June 2005 and March 2003 – June 2005).

Table B-3. Corrective actions requested (grouped by regulatory area), January 2005 - June 2005.

Table B-4. Corrective actions requested (grouped by basin and subbasin), January 2005 – June 2005.

Table B-5. Site history by basin, January 2005 to June 2005.

Table B-6. List of corrective actions requested, March 2003 – June 2005.

Appendix C. Phthalate air monitoring information.